

LANDSLIDES SCARS IN RECIFE/PE - BRAZIL

Landslides Scars

Municipal Boundary

Post-disaster image:
HIRI/Pleiades 1B - 01.06.2022
© CNES (2022), Distribution Airbus DS.

GEOGRAPHIC COORDINATE SYSTEM
DATUM: WGS 84