

# LANDSLIDES SCARS IN RECIFE/PE - BRAZIL


 Landslides Scars



Pre-disaster image: Google Satellites  
Post-disaster image:  
HIRI/Pleiades 1B - 01.06.2022  
© CNES (2022), Distribution Airbus DS.



PROJECTED COORDINATE SYSTEM  
EPSG:32725 - WGS 84 / UTM ZONE 25S



Av. Conde Pereira Carneiro

SCALE: 1:1600

0 25 50 m

9103239

9103132

9103025

283443

283550

283657

283764