

# LANDSLIDES SCARS IN RECIFE/PE - BRAZIL

R. México

 Landslides Scars



Pre-disaster image: Google Satellites  
Post-disaster image:  
HIRI/Pleiades 1B - 01.06.2022  
© CNES (2022), Distribution Airbus DS.



SCALE: 1:1400

0 25 50 m

283550

283657

9103132

9103025

