


LANDSLIDES SCARS IN OLINDA/PE - BRAZIL

 Landslides Scars



Pre-disaster image: Google Satellites
Post-disaster image:
HIRI/Pleiades 1B - 01.06.2022
© CNES (2022), Distribution Airbus DS.



PROJECTED COORDINATE SYSTEM
EPSG:32725 - WGS 84 / UTM ZONE 25S

9114900
9114870
9114840
9114810
9114780

Av. Chagas Ferreira



288930 288960 288990 289020 289050 289080

