



LANDSLIDES SCARS IN OLINDA/PE - BRAZIL



 Landslides Scars



Pre-disaster image: Google Satellites
Post-disaster image:
HIRI/Pleiades 1B - 01.06.2022
© CNES (2022), Distribution Airbus DS.



PROJECTED COORDINATE SYSTEM
EPSG:32725 - WGS 84 / UTM ZONE 25S