

LANDSLIDES SCARS IN RECIFE/PE - BRAZIL

 Landslides Scars



Pre-disaster image: Google Satellites
 Post-disaster image:
 HIRI/Pleiades 1B - 01.06.2022
 © CNES (2022), Distribution Airbus DS.



PROJECTED COORDINATE SYSTEM
 EPSG:32725 - WGS 84 / UTM ZONE 25S



9107500

9107250

SCALE: 1:3000

0 25 50 m

278980

279240