


São Sebastião (Boiçucanga/Camburi) - SP
Geomorphological Processes - Scars and Deposits
Charter Activation 803
2023-03-05

Landslides inferred from post-disaster image HIRI/Pleiades 1A-25.02.2023
Contour lines extracted from JAXA/METI ALOS PALSAR AP26854_FBS_F6700




Camburi beach

Boiçucanga beach

Stream
Contour (10m)

- Landform/Process
- Slide (main body)
 - Slide path
 - Slide foot (deposit)
 - Debris flow fan deposit
 - Debris flow/debris flood in-channel deposit
 - Alluvial (flooding) deposit
 - Mixed deposit (alluvial and debris)
 - Other ruptures (gullies, ravines etc.)



432000 434000 436000 438000 440000

7372000 7370000 7368000